

Download Bmw 318i Sedan 1992 1998 Workshop Service Repair Manual Pdf

Replacing your oil is easy - BMW knows that this needs to be performed once about every 3000-5000 miles, and designed the car that way. On the other hand, the BMW transmissions used on the E36 were supposedly designed with a life-time fluid that did not need to be changed.ate: Comments: initially, sensor for high emissions 1412 and 2440 lit up.Cleaned the valve prior to the smog pump and put it back together. sensor turned off for two days then returned. took 12V direct to actual pump which showed the pump works... but then now the car wont start. tries but doesn't turn over. new codes of 2401, 2419, 1430, and 1413 with restraint bag malfunction on car display.El Club de Diagramas es dónde los técnicos intercambian y comparten diagramas, manuales de servicio y todo archivo de información técnica útil para las reparaciones electrónicas.